

Lab Safety Rules:

- When using any non-encased tool (encased tool being a tool that operates within a closed space like the laser or 3D printers) users must wear proper eye protection.
- Proper hearing protection must be worn while using the Shopbot CNC router.
- No open-toed shoes are permitted in the lab.
- While using any reciprocating tool, hair must be tied back.
- Closely monitor machines that are in use.
- Do not run in the lab.
- Do not bring in any unknown materials into the lab. Check our list of approved materials before bringing anything into the lab. If you are not sure about a material, check with a staff member before bringing it in.
- Aerosols are not permitted in the lab.
- The use of any materials that have harmful fumes are prohibited in the lab.
- Do not use any piece of equipment you do not know how to operate.
- Any form of misconduct towards machines, other users, or Fab Lab staff will lead to an immediate and permanent banishment from the lab.